

Faulty Microchip Information

If your dog was microchipped between the years of 2009 and 2012, there is a chance that their microchip may no longer be readable. It has come to the microchip manufacturer's attention that there were some faulty batches of microchips produced in this time period.

The known faulty batch numbers include:

- From 900-010-000-125-000 to 900-010-000-135-000
- From 900-088-000-032-635 to 900-088-000-543-529
- From 900-008-800-219-506 to 900-008-800-248-955

If you have a vaccination record book, you may find your dog's microchip number in the front section. If not, you can ask your veterinarian to scan the dog next time you are at the clinic. If the microchip is no longer reading, you are entitled to a replacement microchip at the cost of the manufacturer.